


Inner 3 Rows Area



HR100




MOTION & PRESENCE SENSOR



LOT No. _____

Power Supply : AC/DC12~24V±10% 50/60Hz
 Output Contact : Form C Relay
 DC50V 0.1A(Resistor Load)FAIL SAFE MODE
 Wiring : RED&BLACK(Power),WHITE(Common)
 YELLOW(Closed During Detection)
 GREEN(Open During Detection)



MADE IN JAPAN




Quantity of Rows



Inner 3 Rows Area



Outer 2 Rows Area



Outer 2 Rows Area

